

Sensor Let's make sensors more individual



1. Gap - size measurement on an aluminum casting of a turbo charger

The gap – size on the aluminum housing of a turbo charger should be measured. For this purpose, a laser through beam sensor type **L-LAS-TB-F-8x1-40/40** is used. The gap can be proper measured as shown in the screen shots.











