

Application - News

N°550 L-LAS series

Instruments

1. Distance measurement to black rubber band

The distance to a black rubber band should be measured. It has to be taken into account, that the surface of the rubber band can change from black matt to black shiny. For this purpose, a laser displacement sensor type **L-LAS-LT-37** is used at distance of approximately 37mm. The distance can be proper measured as shown in the screenshot.







