



1. Orientation control of metal rods

The correct orientation of metal rods should be controlled. For this purpose, a laser through beam line scan sensor type **L-LAS-TB-F-6x1-100/100-CL** is used. The correct orientation of the metal rods can be properly detected as shown in the screen shots.

